

Dredging Projects (2016)




Figure 1: A map of the dredging projects undertaken in 2016 and their effects on the subsequent drainage patterns in the East River - Moriches Bay, New York. The light blue stars and the quarter-mile circles around them represent the locations dredged.

Coastal Vulnerability Index East River - Moriches Bay Watershed, NY




Figure 2: A Coastal Vulnerability Index (CVI) map of the East River – Moriches Bay, New York. Some areas of concern are densely populated and under further development.